

CAMPANE DA BANCO  
TABLETOP CHAMBERS  
CAMPANAS DE SOBREMESA



Display digitale  
Ciclo di vuoto temporizzato  
Saldatura temporizzata  
Coperchio con pistoni  
Vasca in acciaio stondata  
Barra con pistoni senza fili  
Piano inclinato per liquidi (opz.)



Digital display  
Timed vacuum cycle  
Timed welding  
Lid with pistons  
Round steel tank  
Wireless sealing bars  
Inclined shelf for liquids (opt.)



Display digital  
Ciclo de vacío temporizado  
Soldadura temporizada  
Tapa con pistones  
Cubeta redondeada de acero inoxidable  
Barra con pistones inalámbricos  
Estante inclinado para líquidos (opc.)



BREEZE

DIABLO

CALIMA

TWISTER

Dimensioni macchina Machine dimensions Dimensiones máquina	390x480x380 h mm	510x560x510 h mm	555x550x515 h mm	660x660x530 h mm
Peso Weight Peso	29 kg	39 kg	60 kg	78 kg
Voltaggio Voltage Voltage	110 V-60 Hz ● 230 V-50/60 Hz	110 V-60 Hz ● 230 V-50/60 Hz	110 V-60 Hz ● 230 V-50/60 Hz	110 V-60 Hz ● 230 V-50/60 Hz
Consumo Power consumption Consumo	1.1 kW	1.0 kW	1.05 kW	1.15 kW
Dimensioni camera Chamber dimensions Dimensiones cámara	270x350x190 h mm	370x440x210 h mm	430x430x220 h mm	530x530x235 h mm
Pompa Pump Bomba	6 m3 /h DVP	8 m3 /h DVP	12/20 m3 /h DVP	20 m3 /h DVP
Barra saldante Welding bar Barra de soldadura	260 mm	365 mm	420 mm	520 mm
Piano inclinato per liquidi (acc.) Liquids inclined shelf (acc.) Estante inclinado para líquidos (acc.)	✓	✓	✓	✓
Vuotometro (opz.) Vacuum gauge (opt.) Vacuómetro (opc.)	×	✓	✓	✓
Predisposizione vuoto teglie GN (opz.) Vacuum in GN pans prearrangement (opt.) Predisposición vacío en bandejas GN (opc.)	Incluso Included Incluido	Incluso Included Incluido	Incluso Included Incluido	Incluso Included Incluido

● Voltaggio speciale su richiesta


Special voltage on demand

Voltaje especial a petición

CAMPANE DA BANCO  
TABLETOP CHAMBERS  
CAMPANAS DE SOBREMESA



DIABLO



1 Pulsante alimentazione macchina	Power on/off button	Botón encendido máquina
2 Display di visualizzazione tempo di vuoto	Vacuum time display	Display del tiempo de vacío
3 Display di visualizzazione tempo di saldatura	Sealing time display	Display visualización del tiempo de soldadura
4 Pulsanti regolazione tempo di vuoto (secondi)	Adjusting vacuum time (seconds) buttons	Botón de selección del tiempo de vacío
5 Pulsanti regolazione tempo di saldatura (secondi)	Adjusting sealing time (seconds) buttons	Botón de regulación del tiempo de soldadura (segundos)